

Jan 29 14:42:07 TRM_0201_201 kernel: [13579722.441387] e1000: eth0: e1000_watchdog: NIC Link is Down <최초 장애>

Jan 29 14:42:07 TRM_0201_201 kernel: [13579722.566210] br0: port 1(eth0) entering disabled state
Jan 29 14:42:13 TRM_0201_201 kernel: [13579727.913396] e1000: eth0: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex
Jan 29 14:42:13 TRM_0201_201 kernel: [13579728.013639] br0: port 1(eth0) entering learning state
Jan 29 14:42:14 TRM_0201_201 kernel: [13579729.012963] br0: topology change detected, propagating
Jan 29 14:42:14 TRM_0201_201 kernel: [13579729.012976] br0: port 1(eth0) entering forwarding state
Jan 29 14:42:26 TRM_0201_201 kernel: [13579741.033581] e1000: eth0: e1000_watchdog: NIC Link is Down
Jan 29 14:42:26 TRM_0201_201 kernel: [13579741.137008] br0: port 1(eth0) entering disabled state
Jan 29 14:42:29 TRM_0201_201 kernel: [13579743.753125] e1000: eth0: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex
Jan 29 14:42:29 TRM_0201_201 kernel: [13579743.854233] br0: port 1(eth0) entering learning state
Jan 29 14:42:30 TRM_0201_201 kernel: [13579744.853555] br0: topology change detected, propagating
Jan 29 14:42:30 TRM_0201_201 kernel: [13579744.853568] br0: port 1(eth0) entering forwarding state
Jan 29 14:44:59 TRM_0201_201 kernel: [13579893.929727] e1000: eth0: e1000_watchdog: NIC Link is Down
Jan 29 14:44:59 TRM_0201_201 kernel: [13579894.035222] br0: port 1(eth0) entering disabled state
Jan 29 14:45:03 TRM_0201_201 kernel: [13579898.401528] e1000: eth0: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex
Jan 29 14:45:03 TRM_0201_201 kernel: [13579898.506637] br0: port 1(eth0) entering learning state
Jan 29 14:45:04 TRM_0201_201 kernel: [13579898.783537] e1000: eth0: e1000_watchdog: NIC Link is Down
Jan 29 14:45:04 TRM_0201_201 kernel: [13579899.505956] br0: topology change detected, propagating
Jan 29 14:45:04 TRM_0201_201 kernel: [13579899.505969] br0: port 1(eth0) entering forwarding state
Jan 29 14:45:04 TRM_0201_201 kernel: [13579899.510615] br0: port 1(eth0) entering disabled state
Jan 29 14:45:06 TRM_0201_201 kernel: [13579901.501302] e1000: eth0: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex
Jan 29 14:45:07 TRM_0201_201 kernel: [13579901.601612] br0: port 1(eth0) entering learning state
Jan 29 14:45:08 TRM_0201_201 kernel: [13579902.600923] br0: topology change detected, propagating
Jan 29 14:45:08 TRM_0201_201 kernel: [13579902.600936] br0: port 1(eth0) entering forwarding state
Jan 29 14:45:16 TRM_0201_201 kernel: [13579911.332703] e1000: eth0: e1000_watchdog: NIC Link is Down
Jan 29 14:45:16 TRM_0201_201 kernel: [13579911.443124] br0: port 1(eth0) entering disabled state
Jan 29 14:45:19 TRM_0201_201 kernel: [13579914.051247] e1000: eth0: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex
Jan 29 14:45:19 TRM_0201_201 kernel: [13579914.154175] br0: port 1(eth0) entering learning state
Jan 29 14:45:20 TRM_0201_201 kernel: [13579915.152677] br0: topology change detected, propagating
Jan 29 14:45:20 TRM_0201_201 kernel: [13579915.152691] br0: port 1(eth0) entering forwarding state
Jan 29 15:47:22 TRM_0201_201 kernel: [13583634.949056] e1000: eth1: e1000_watchdog: NIC Link is Down
Jan 29 15:47:22 TRM_0201_201 kernel: [13583635.053886] br0: port 2(eth1) entering disabled state
Jan 29 15:47:25 TRM_0201_201 kernel: [13583638.602393] e1000: eth1: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex
Jan 29 15:47:25 TRM_0201_201 kernel: [13583638.703517] br0: port 2(eth1) entering learning state
Jan 29 15:47:26 TRM_0201_201 kernel: [13583639.702828] br0: topology change detected, propagating
Jan 29 15:47:26 TRM_0201_201 kernel: [13583639.702841] br0: port 2(eth1) entering forwarding state
Jan 29 16:20:01 TRM_0201_201 kernel: [13585593.361471] e1000: eth0: e1000_watchdog: NIC Link is Down
Jan 29 16:20:01 TRM_0201_201 kernel: [13585593.466305] br0: port 1(eth0) entering disabled state
Jan 29 16:20:08 TRM_0201_201 kernel: [13585600.707471] e1000: eth0: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex
Jan 29 16:20:08 TRM_0201_201 kernel: [13585600.808496] br0: port 1(eth0) entering learning state
Jan 29 16:20:09 TRM_0201_201 kernel: [13585601.807816] br0: topology change detected, propagating
Jan 29 16:20:09 TRM_0201_201 kernel: [13585601.807828] br0: port 1(eth0) entering forwarding state
Jan 29 16:20:21 TRM_0201_201 kernel: [13585613.822438] e1000: eth0: e1000_watchdog: NIC Link is Down
Jan 29 16:20:21 TRM_0201_201 kernel: [13585613.925861] br0: port 1(eth0) entering disabled state

Jan 29 16:20:24 TRM_0201_201 kernel: [13585616.561976] e1000: eth0: e1000_watchdog: NIC Link is Up 1000 Mbps Full Duplex <KT 장비 교체>

Jan 29 16:20:24 TRM_0201_201 kernel: [13585616.664078] br0: port 1(eth0) entering learning state
Jan 29 16:20:25 TRM_0201_201 kernel: [13585617.663398] br0: topology change detected, propagating
Jan 29 16:20:25 TRM_0201_201 kernel: [13585617.663412] br0: port 1(eth0) entering forwarding state